



# **Hindu Temple of Florida**

## **Projects for 2014-15**

### **New Temple Annex:**

**1. Gopurams : \$50,000.00**

Gopurams for 2 new shrines - \$25,000.00 each

The Shilpis from India are currently working on this project

Navagraha Gopuram – completed as of October 2014 – needs painting

Gopuram for Lord Anjaneya , Sri. Shirdi Saibaba to be completed .

**2. Air conditioning: \$50,000.00**

Air conditioning – Heating of the New Shrines and the common area of the new temple annex

–Quote - \$50,000.00

Centralized air conditioning and heating of the new Temple Complex

Present structure has the room for this installation, but was not of the initial structural cost

**3. Indianization : \$50,000.00**

Indianization of the new Annex and the Temple Prasad Sadan : Estimate -\$50,000.00

Architectural indianization of new shrine building and the temple canteen to match the current main Temple .

This project will have required embellishments – plant to be completed in three months, as soon as the Gopurams are completed.

Shilpis are required to stay for this project and time is of essence.



## **Hindu Temple of Florida**

### **Projects for 2014 -2015**

#### **1. Painting : \$50,000.00**

The main temple building , including upstairs and downstairs , inside and outside .

All the Vimana Gopuram, The main Raja Gopuram, The outside indianization architecture .

It involves pressure washing, base coat and the painting .

#### **2. Temple Parikrama Flooring ( upstairs) : \$35,000.00**

Involves the completion of the flooring, upstairs, both in front of the Temple and the parikrama ,

The material used will be the one used for the deck surfacing

The material should not heat up , as people perform the pradakshina around the Temple.

The material should not be slippery when it rains

The color should be neutral and pleasing

#### **3. Landscaping of the Temple premises: ( basic) \$25,000.00**

New constructions currently underway will be completed by May 2015

Complete the basic landscaping around the temple

Making sure the plants require low maintenance, create adequate walkways, adequate lights.



### **Hindu Temple of Florida**

#### **4. Temple Hall Renovation: \$50,000.00**

The temple Hall stage and the rear bathrooms need to be renovated .

#### **5. Audio- Visual Both upstairs and down stairs: \$25,000.00**

There is no good audio-visual system at this time either at the Temple or Hall

There is no close circuit TV system to beam the important events in the Hall.

Need to install TVs and the new audio system with the capabilities

The large screen in the Community Hall and the projection system needs to be  
Fixing

#### **6. Lighting : Both inside and outside landscape lighting : \$15,000.00**

Presently there is minimal lighting around the temple

Lights need to be added / upgraded both inside the temple Hall upstairs and down stairs.

Stage Lights to be added.

Landscaping lighting to be designed once the new landscaping is done.

#### **7. Debt reduction : \$800,000.00**

The total debt from the inception after the consolidation of all debts is \$800,00.00